

Архангельск (8182)63-90-72
Астана (7172)727-132
Астрахань (8512)99-46-04
Барнаул (3852)73-04-60
Белгород (4722)40-23-64
Брянск (4832)59-03-52
Владивосток (423)249-28-31
Волгоград (844)278-03-48
Вологда (8172)26-41-59
Воронеж (473)204-51-73
Екатеринбург (343)384-55-89
Иваново (4932)77-34-06

Ижевск (3412)26-03-58
Иркутск (395)279-98-46
Казань (843)206-01-48
Калининград (4012)72-03-81
Калуга (4842)92-23-67
Кемерово (3842)65-04-62
Киров (8332)68-02-04
Краснодар (861)203-40-90
Красноярск (391)204-63-61
Курск (4712)77-13-04
Липецк (4742)52-20-81

Магнитогорск (3519)55-03-13
Москва (495)268-04-70
Мурманск (8152)59-64-93
Набережные Челны (8552)20-53-41
Нижний Новгород (831)429-08-12
Новокузнецк (3843)20-46-81
Новосибирск (383)227-86-73
Омск (3812)21-46-40
Орел (4862)44-53-42
Оренбург (3532)37-68-04
Пенза (8412)22-31-16

Пермь (342)205-81-47
Ростов-на-Дону (863)308-18-15
Рязань (4912)46-61-64
Самара (846)206-03-16
Санкт-Петербург (812)309-46-40
Саратов (845)249-38-78
Севастополь (8692)22-31-93
Симферополь (3652)67-13-56
Смоленск (4812)29-41-54
Сочи (862)225-72-31
Ставрополь (8652)20-65-13

Сургут (3462)77-98-35
Тверь (4822)63-31-35
Томск (3822)98-41-53
Тула (4872)74-02-29
Тюмень (3452)66-21-18
Ульяновск (8422)24-23-59
Уфа (347)229-48-12
Хабаровск (4212)92-98-04
Челябинск (351)202-03-61
Череповец (8202)49-02-64
Ярославль (4852)69-52-93

Киргизия (996)312-96-26-47

Россия (495)268-04-70

Казахстан (772)734-952-31

<https://qianzhu.nt-rt.ru/> || quz@nt-rt.ru

X5015

Heavy-duty tapered roller bearing spindle



Enquiry

Detail

Specifications

Max .Drilling capacity

Face mill capacity

End mill capacity

Working table size

Working table travel

Vertical travel

Spindle stroke

Max distance spindle to table

Head tilt left and right

Spindle taper

Spindle speed range

1 Speed

motor 1.125KW (standard):

Number of speeds

N.W/G.W

Packing dimension (w/o stand)

Features :

Milling drilling,tapping,boring,reaming

Headstock can rotated and tilted

Heavy-duty tapered roller bearing spindle

Positive spindle lock

Adjustable gibs on table

Z axis screw drive

Micro feed precision

Options:

“S”- Machine stand; “W”-Work table power feeder; “R”-Digital read out (DRO);

P1:X5015(S)

Units

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

mm

rpm

(steps)

kg

mm

X5015

20

60

20

660×152

370×150

195

89

345

90°

MT3 or R8

200-2500

9

300/350

930×760×1260